

--

Climax Molybdenum Company P.O. Box 220 Fort Madison, Iowa 52627 (319) 463-7151

August 31, 2006

06ENV-039

US EPA Region 7
Federal Building
210 Walnut Street, Room 473
Des Moines, IA 50309-2109
Attn: Gary Witkovski

Subject: Climax Molybdenum Company EPA RCRA ID# IAD000222653

Initial Response for RCRA Audit Performed on 08/22/2006

Dear Mr. Witkovski,

NEGU

RESP

This letter contains our initial written responses to the findings from your site inspection conducted on August 22, 2006 at our facility in Fort Madison, Iowa. Per your request, we are sending this initial response within 14 days, but it does not contain the requested analytical testing results, which takes more than 14 days to obtain. The results of the testing will be forwarded to you upon receipt from the testing laboratory. Our responses follow below:

Alleged Violation No. 1 40CFR 279.22(C) Used oil containers

Used oil containers not labeled "Used Oil"

On August 22, 2006, at your suggestion, we labeled the drums at issue "Used Oil", placed suitable covers on the drums, and covered the drums on the pallet with plastic while they are awaiting use. During the inspection, we indicated that this material was not used, but rather virgin product for which we had not obtained alternate use. We continue to investigate alternate uses for this product.

Upon closer review of the definition of "used oil" (any oil that has been refined from crude oil, or any synthetic oil that has been used and as a result of such use is contaminated by physical or chemical impurities 40 CFR 279.1), we do not believe that the material qualifies as used oil because the material remaining in the drums has never been used and is not contaminated by physical or chemical impurities. As such, we believe that the alleged violation should be rescinded.

Alleged Violation No. 2 40CFR 262.11 Failure to make hazardous waste determinations on:

- a. Baghouse dust
- b. Spent parts washer solvent

On August 23, 2006, we obtained samples from the drum under the welder baghouse and from the drum containing used Electra 221 parts washer solvent in the maintenance shop. The samples have been submitted to the University Hygienic Laboratory in Ankeny, Iowa for TCLP testing. The results from these analyses will be forwarded to your attention upon receipt.

Based on knowledge of the processes generating these two waste streams, we have no reason to believe that the streams are "hazardous" waste. This knowledge is based on prior TCLP analyses on these products and is properly documented in our files.

470513



The TCLP data for the spent parts washer solvent was found and available during the site inspection on August 22, 2006. The analytical information is attached for your information. The data is from February 2005, and the present parts washer solvent has been in use at the site since 2003 per our purchasing records and is the same part washer solvent observed during the site inspection. As such, we believe these waste streams to be non-hazardous.

For the baghouse dust, utilizing process knowledge and prior TCLP testing found the material to be non-hazardous. The principal components of the baghouse dust are glass beads from our blasting process and floor sweepings from the maintenance shop. Both of these materials have been characterized individually and the TCLP testing completed shows the components to each be non-hazardous for toxicity. Each component does not exhibit any other hazardous waste characteristic and have not been mixed with a listed hazardous waste. As each of the components entering the baghouse have been determined to be non-hazardous, process knowledge leads to the determination that the baghouse dust is non-hazardous as well. The analytical information for the glass beads and floor sweepings is attached for your reference.

As mentioned previously, we will forward to you the results of the most recent laboratory analysis on the samples you requested when they are received by us.

Based on the foregoing, we respectfully request that the notices of violation be rescinded.

If you have any questions, please contact me at (319) 463-2224.

Sincerely,

Scott Ickes

Manager of QA and Environmental Affairs

Climax Molybdenum Co.

SW940815

TCLP Analysis

Date: 8-25-99

Technician:

IV. Final Test Results

	Test	Hazardous
Parameter (mg/l)	Results	Limits
Arsenic	4.1	5.0
Barium	<1	100.0
Cadmium	.35	1.0
Chromium	2.9	5.0
Lead	<1.0	5.0
Mercury	<.1	0.2
Selenium	.93	1.0
Silver	<1	5.0
		У4

Classification

Hazardous

Nonhazardous

TCLP Analysis Worksheet

Date:	8-24-94	8-25-94
Technician:		

III. Extraction Fluid Determination

	18
Initial pH check (pH < 5 use Ext. #1;)pH > 5 add acid)	3.52
Acidifiec pH check (pH < 5 use Ext. #1; pH > 5 use Ext. #2)	
Extraction Fluid Used	1 2
Extraction Fluid pH check	4.98
Initial Ext. Fluid + sample pH	4.30

4.32

Filtrate Container Tare wt.		
Sample Container Tare wt.	12	
Filter Paper Tare wt		
Filtrate container + Filtrate wt		
Filtrate wt.		
Filtrate Volume		
Sample Container + Sample wt		
Sample wt	100.0	1
Sample Container + Adhered wt		
Adhered wt.		
True Sample wt	100.0	1
Weight of Extraction Fluid used (20 X %Solids X True Wt. / 100)	1942	10
Vol of Extraction Fluid used	1942	1
Extraction Fluid pH	4.98	2

Initial Extraction Start Time	9-14-94	A/a
	2-11	NOON
Final Extraction Time	8-25-91	3:00 10
Liquid Phase Extraction vol		
pH After Extraction		4.20

100N 7:00 km

4.19

TCLP Analysis Worksheet

I. Sample Information

Sample Name	FLOOR SWEEPINGS		
Sample No.	SW940815		
Date Sampled	UNKNOWN		
Sample Method	לא בני פני אני ט		
Sample Location	LANGLOTH		
Sampler	unknown		

FLOOR	Sweepings	from	LANGLOTH
	- 0		
			¥

Sample from Parts Washer, Used 2-Feb-05

Based on ICP Scans

		Conc.	D			Unkown	TCLP	7
l		High Std.	Blank	High Std.	Unkown	Estimated	Limit	
Element	Wavelength	mg/L	Counts	Counts	Counts	mg/L	mg/L	
As2	193.695	5	1215	3160	1043	<0.50	5.0	7
Ba1	455.403	100	1843	5318872	2509	0.3	100.0	7
Cd1	214.438	1	1965	26027.5	2214	0.2	1.0	1
Cr3	206.149	5	1662	24417	1398	<0.5	5.0	٦
Pb1**	220.353	5	2417	12595.5	2891	4.7	5.0	**
Hg9	194.163						0.2	7
Se1**	196.026	1	1299	1482.5	1057	<0.10	1.0	7
Ag1	328.068	15	597	13690	788	4.4	5.0	**
Mn1	257.61							1
Mo1	202.03	100	1576	332534	19122	106.0		1
Cu1	324.754	5	1117	26837	2361	4.8		1
Ni3	231.604	5	284	1773.5	442	10.6		1
Fe2	259.94	5	439	6339.5	2124	28.6		7

^{**} The Pb and Ag analysis are probably not this high. Looking at the scans, the error on the high side is most likely due to dilution and the inherent variance of the scans.

Sample preparation: 5 mls sample + 45 mls D.I. water + 10 mls HNO $_{\rm 3}$ acid.

Boil, reduce to 10 mls volume.

Add 10 mls of HNO₃, cover and reflux for 15 minutes.

Uncover, evaporate to 5 mls, cool, and dilute to 100 mls.

This checklist can be used as a tool to help classify waste materials and document the determination process. Federal and state EPA regulations require generators of *waste* to determine whether a waste is hazardous and document information used in the hazardous waste determination .

GENERAL INFORMATION

Plant Name	: Climax Moybdenum Company
Waste Name	: Climax Moybdenum Company Harts washer Solvent
MATERIAL IDI	ENTIFICATION
material safety dai	formation related to the waste material that is generated. Reviewing the a sheet(s) (MSDSs) and having knowledge of the process(es) and wastes we beneficial when completing this section.
Waste Stream Nar	ne or Waste Identification #: Forts Washer Solvent
	1: MAinknance Shop
Specify the genera constituents and/or	material, including the physical state (i.e. solid, liquid, gas), known hable, corrosive, toxic), expected or known constituents, and % if known. tion process including raw materials used, residuals (i.e. dissolved metals), etc. MSD Attached Used to the former factor of the content of the
MAINTEN SAFEN KI	me farts Spent Solvent recycled by

WASTE DETERMINATION (Check all that apply)

The first step in the classification process is to determine whether the material meets the definition of a waste. To make this determination, check each box that applies to the material. Once complete; review waste exclusions (40 CFR 261.4) to determine if the material is excluded from the definition of a waste. It is important to remember when proceeding through this section that the definition of a waste is very broad and includes solids, semisolids, liquids, or confined gases.

The	e material is being abandoned (40 CFR 261.2 (b)) Disposed of; Burned or incinerated; Accumulated, stored, or treated, but not recycled, before or in place of being discarded by being disposed of, burned or incinerated
The mar	e material is being recycled, or accumulated, stored or treated before recycling and is naged as indicated below (40 CFR 261.2 (c)) Handled in a manner constituting disposal Burned for energy recovery Reclaimed Accumulated speculatively for the purpose of recycling
The	material is inherently waste-like when recycled (40 CFR 261.2 (d)) Federal EPA Hazardous Waste Code numbers F020, F021, F022, F023, F026, & F028 Secondary materials fed to a halogen acid furnace that exhibit characteristics of a Hazardous waste, except for brominated material.

WASTE EXCLUSIONS (40 CFR 261.4)

There are some exclusions that pertain to wastes which are excluded from the definition of a waste and/or hazardous waste, such as domestic sewage, National Pollution Discharge Elimination System (NPDES) permitted discharges, spent sulfuric acid used to produce virgin sulfuric acid, radioactive materials, laboratory wastes, cement kiln dust, wastes generated in process units, household wastes, mining wastes, some scrap metals, and others. Review the exclusions listed in 40 CFR 261.4 and determine whether or not your material is excluded. Once the waste exclusions have been reviewed, proceed to check the box below which indicates the result of your waste determination.

None of the boxes were checked. Thus, the material is **not** considered a waste. **Proceed to** the Determination Section.

At least one box was checked. The material has been determined to be a waste. However, upon reviewing the exclusions in 40 CFR 261.4, it has been determined that the material is excluded from the definition of a waste. Therefore, the material is not considered a waste and is not a hazardous waste. **Proceed to the Determination Section.**

At least one box was checked. The material has been determined to be a waste and is not excluded from the waste definition per 40 CFR 261.4. To determine whether or not the waste is a hazardous waste, Proceed to the next Section (Hazardous Waste Determination).

HAZARDOUS WASTE DETERMINATION

FEDERAL RCRA LISTED WASTES [40 CFR 261.31-33] (Check any that apply)

This section was designed to assist you in determining whether or not your waste is a Federal Resource Conservation and Recovery Act (RCRA) hazardous waste. Review each step and refer to the attached lists or noted regulations in order to fully determine whether or not the waste or process is located on a list. Check each box that applies to your waste and indicate the Federal EPA Hazardous Waste Code (e.g. F006, U093...) in the space provided. When your waste/process has been matched against each list, a determination has been made, and the appropriate box(es) has been checked, proceed to the next section.

Process Wastes

	It is a listed waste from a non-specific (generic) process under the "F" listed waste codes [40 CFR 261.31] WASTE CODE :
	It is a listed waste from a specific process under the "K" listed waste codes
	[40 CFR 261.32] WASTE CODE:
×	It is not a listed waste under the "F" or "K" listed waste codes.
Di	scarded Commercial Products/Off-spec Products/Container and Spill Residue
	The sole active ingredient is a listed non-process acute waste per 40 CFR 261.33
	("P" code) WASTE CODE:
	"P" code wastes are considered acutely hazardous wastes (AHW).
	The sole active ingredient is a listed non-process toxic waste per 40 CFR 261.33
	("U" code) WASTE CODE:
	"U" code wastes are used for wastes that are considered toxic, reactive, ignitable, or corrosive.
Ž.	It is not a listed waste under the "P" or "U" listed waste codes.
/\ _	None of the boxes were checked. Thus, the material is not considered a waste.
No	te: if a listed ingredient is not the sole active ingredient, then it is not considered a "U" or
"P'	'waste code.

Proceed to the next Section (Hazardous Waste Physical Characteristics) when complete.

HAZARDOUS WASTE PHYSICAL CHARACTERISTICS (Check all that apply) Below are hazardous waste physical characteristics that may assist you in the process of properly determining whether your waste is hazardous. Reviewing MSDS(s) and other sources of information may be beneficial when completing this section, especially without the use of laboratory analyses. The characteristics of the waste may be obtainable through generator knowledge and/or laboratory analyses. However, it is important to remember that it is the sole responsibility of the generator to properly determine whether the waste is hazardous or not. Be sure you have data to back your determination!

Tł	ne waste is ignitable per 40 CFR 261.21 (EPA Hazardous Waste Code: D001)
	Liquid with a flashpoint < 140°F /487
	Solid capable of causing fire by friction, absorption of moisture, or spontaneous chemical change
	Compressed gas as defined by 49 Code of Federal Regulations 49 CFR173.300 Material has a pressure > 40 psi @ 70°F or vapor pressure > 40 psi absolute @ 100°F
	Oxidizer as defined by 49 CFR 173.151
-	Releases oxygen when reacting with another chemical
-	Reacts with organic materials (e.g. oils, grease, solvents, paper, cloth, wood, etc.) resulting in fire or generation of heat
	Wastes which may meet this criteria include: solvents, paints, thinners, and adhesives
Th	e waste is corrosive per 40 CFR 261.22 (EPA Hazardous Waste Code: D002)
	Aqueous (liquid) and has a pH < 2 (acid) or > 12.5 (base)
	Solid (non-liquid) when mixed with equal weight of water has a pH < 2 (acid) or > 12.5 (base)
<u> </u>	Dissolves/corrodes steel (SAE 1020) at a rate greater than .25 inch per year Wastes which may meet this criteria include: etchants, alkaline degreasers, acids and base
Th	e waste is reactive per 40 CFR 261.23 (EPA Hazardous Waste Code: D003)
	Normally unstable & readily undergoes violent change without detonation
	Reacts violently with water, or forms potentially explosive mixtures with water
	Generates toxic gases, vapors or fumes when mixed with water or air
	Capable of detonation, explosive reaction or explosive decomposition
	Wastes which may meet this criteria include: chromic acids and cyanide compounds

The waste is **toxic** per 40 CFR 261.24 (EPA Hazardous Waste Code: Varies)

Determining whether or not a waste is hazardous due to its toxicity can be a very complicated process. The toxicity characteristic is the most complex characteristic to determine. This characteristic is based on whether or not a waste exceeds concentrations of certain metals and organics based on analytical results from laboratory analyses. The collection and submission of waste samples for each laboratory analysis can become an expensive endeavor. However, it is important to realize that the generator can save a significant amount of money by better understanding the process and the waste generated by the process. Thus, possibly eliminating or reducing the number of samples needed to properly characterize the waste.

Next, are some hazardous waste tables that may be used to assist you in properly characterizing waste streams. In the tables you will find the name of the constituent and the regulatory limit for that constituent and that particular test. During this phase there are

California (Non-RCRA) regulatory limits and Federal (RCRA) regulatory limits. So, be sure to select which test(s) will provide you with the best results to properly classify your waste. The next five tables consist of substances which are known to be hazardous at/above certain regulatory concentrations. The following tables provide you with the constituents and their regulatory limits associated with a specific laboratory analysis. If you are using laboratory analysis results to aid in the determination of your waste, then proceed to check the appropriate box(es) for each constituent that meets and/or exceeds the regulatory limit in the, particular table. If you still have questions regarding toxicity analyses, then proceed to the last page where you can find some additional information regarding toxicity analysis for wastes.

TABLE 1

Threshold Characteristic Leaching Procedure (TCLP) [RCRA] – This analysis helps determine whether a facility's waste is a RCRA hazardous waste and is the least expensive. This analysis should be the first step if you are uncertain what may be in your wastestream or you suspect that your wastestream contains any of the constituents listed below. Compare analytical data to the constituents listed below and determine whether they meet or exceed the regulatory limits in the table. Check the appropriate box(es). If no constituents are identified at or above the listed regulatory limit, proceed to Table 2. Note: The EPA Hazardous Waste Code (in parenthesis) is located next to the regulatory concentration limit for each constituent.

TCLP (mg/l) [40 CFR 261.24(b)(1)]

- ☐ Arsenic > 5.0 mg/l (D004)
- ☐ Barium >100 mg/l (D005)
- ☐ Benzene >0.5 mg/l (D018)
- □ Cadmium >1.0 mg/l (D006)
- ☐ Carbon Tetrachloride >0.5 mg/l (D019)
- ☐ Chlordane >0.03 mg/l (D020)
- ☐ Chlorobenzene >100 mg/l (D021)
- □ Chloroform >6.0 mg/l (D022)
- ☐ Chromium >5.0 mg/l (D007)
- □ o-cresol >200.0 mg/l (D023)
- ☐ m-cresol >200.0 mg/l (D024)
- □ p-cresol >200.0 mg/l (D025)
- ☐ Cresol >200.0 mg/l (D026)
- \square 2,4-D > 10.0 mg/l (D016)
- □ 1,4-Dichlorobenzene >7.5 mg/l (D027)
- □ 1,2-Dichloroethane >0.5 mg/l (D028)
- □ 1,1-Dichloroethylene >0.7 mg/l (D029)
- □ 2,4-Dinitrotoluene >0.13 mg/l (D030)
- ☐ Endrin >0.02 mg/l (D012)
- ☐ Heptachlor(and epoxide) >.008 mg/l (D031)
- ☐ Hexachlorobenzene >.13 mg/l (D032)
- ☐ Hexachlorobutadiene >0.5 mg/l (D033)
- ☐ Hexachloroethane >3.0 mg/l (D034)
- ☐ Lead > 5.0 mg/l (D008)
- ☐ Lindane >0.4 mg/l (D013)
- ☐ Mercury >0.2 mg/l (D009)
- ☐ Methoxychlor >10.0 mg/l (D014)
- ☐ Methyl ethyl ketone >200.0 mg/l (D035)
- □ Nitrobenzene >2.0 mg/l (D036)
- ☐ Pentachlorophenol >100.0 mg/l (D037)

	Pyridine >5.0 mg/l (D038) Selenium >1.0 mg/l (D010) Silver >5.0 mg/l (D011) Tetrachloroethylene >0.7 mg/l (D039) Toxaphene >0.5 mg/l (D015) Trichloroethylene >0.5 mg/l (D040) 2,4,5-Trichlorophenol >400.0 mg/l (D041) 2,4,6-Trichlorophenol >2.0 mg/l (D042) 2,4,5-TP (Silvex) >1.0 mg/l (D017) Vinyl Chloride >0.2 mg/l (D043) No testing was conducted.
Thi kno	DITIONAL INFORMATION (Check if applies) s waste has been classified using some form of generator knowledge (MSDS, wledge of similar wastes or process knowledge, etc.). See attached documents which port this determination.
The Oth Rea	material is a hazardous waste. material is a non-hazardous waste. er (i.e. universal waste, special waste, etc.). soning: Material does not contain hazardous onstituents nor is st flammaslu, foxic or orrowre.
Note	e: attach any and all documentation (i.e. MSDSs, laboratory analyses, generator wledge, calibration records, etc.) associated with the determination of this waste.
This facil	waste may be disposed of at the following ities:
re	iginal 2/23/96 Vised 12/14/98 rised 2/05

GB \$3\$3114

TCLP Analysis Worksheet

I. Sample Information

Sample Name	Glass Blantha Beads USED
Sample No.	Glass Blanting Beads USED GB Ø3Ø311U
Date Sampled	MARCH 11, 2003
Sample Method	MARCH 11, 2003 GRAB
Sample Location	Blasting Cabinet
Sampler	1. Batholomers

omments:		
·		Series Control of the
	(0)	
_		

TCLP Analysis

Date: 4-8-9-9-07
Technician: 9-19-athology

GB Ø3 Ø311 U

GHSS BENds USEd

A 6 months Used

IV. Final Test Results

	Parameter (mg/l)	Test Results	Hazardous Limits
4-8-03	Arsenic	< 4.007	5.0
	Barium	<10	100.0
4-9-07	Cadmium	< 4.1	1.0
4-9-07	Chromium	<φ.5	5.0
4-9-03	Lead	<φ.5	5.0
	Mercury UHL	<.0002	0.2
4-8-03	Selenium	4.011	1.0
	Silver UHL	<.01	5.0
4-9-03	Mo	2.0	NA

Classification

Hazardous

This checklist can be used as a tool to help classify waste materials and document the determination process. Federal and state EPA regulations require generators of *waste* to determine whether a waste is hazardous and document information used in the hazardous waste determination .

GENERAL INFORMATION
Plant Name : Clinax Moly b denum Campany
Plant Name : ClimAx Moly b denum lampany Waste Name : BAd blast media
MATERIAL IDENTIFICATION
Provide general information related to the waste material that is generated. Reviewing the material safety data sheet(s) (MSDSs) and having knowledge of the process(es) and wastes generated may prove beneficial when completing this section.
Waste Stream Name or Waste Identification #: Lad blast media
Area of Generation: Maintenance Area
Describe the waste material, including the physical state (i.e. solid, liquid, gas), known hazards (i.e. flammable, corrosive, toxic), expected or known constituents, and % if known. Specify the generation process including raw materials used, residuals (i.e. dissolved constituents and/or metals), etc.
Solid Sends from Sand Stasting in
17 HINTEN HALL TITES

WASTE DETERMINATION (Check all that apply)

The first step in the classification process is to determine whether the material meets the definition of a waste. To make this determination, check each box that applies to the material. Once complete; review waste exclusions (40 CFR 261.4) to determine if the material is excluded from the definition of a waste. It is important to remember when proceeding through this section that the definition of a waste is very broad and includes solids, semisolids, liquids, or confined gases.

The	e material is being abandoned (40 CFR 261.2 (b)) Disposed of; Burned or incinerated; Accumulated, stored, or treated, but not recycled, before or in place of being discarded by being disposed of, burned or incinerated
The man	material is being recycled, or accumulated, stored or treated before recycling and is naged as indicated below (40 CFR 261.2 (c)) Handled in a manner constituting disposal Burned for energy recovery Reclaimed Accumulated speculatively for the purpose of recycling
The	material is inherently waste-like when recycled (40 CFR 261.2 (d)) Federal EPA Hazardous Waste Code numbers F020, F021, F022, F023, F026, & F028 Secondary materials fed to a halogen acid furnace that exhibit characteristics of a Hazardous waste, except for brominated material.

WASTE EXCLUSIONS (40 CFR 261.4)

There are some exclusions that pertain to wastes which are excluded from the definition of a waste and/or hazardous waste, such as domestic sewage, National Pollution Discharge Elimination System (NPDES) permitted discharges, spent sulfuric acid used to produce virgin sulfuric acid, radioactive materials, laboratory wastes, cement kiln dust, wastes generated in process units, household wastes, mining wastes, some scrap metals, and others. Review the exclusions listed in 40 CFR 261.4 and determine whether or not your material is excluded. Once the waste exclusions have been reviewed, proceed to check the box below which indicates the result of your waste determination.

None of the boxes were checked. Thus, the material is **not** considered a waste. **Proceed to the Determination Section.**

At least one box was checked. The material has been determined to be a waste. However, upon reviewing the exclusions in 40 CFR 261.4, it has been determined that the material is excluded from the definition of a waste. Therefore, the material is not considered a waste and is not a hazardous waste. **Proceed to the Determination Section.**

At least one box was checked. The material has been determined to be a waste and is not excluded from the waste definition per 40 CFR 261.4. To determine whether or not the waste is a hazardous waste, Proceed to the next Section (Hazardous Waste Determination).

HAZARDOUS WASTE DETERMINATION

Process Wastes

FEDERAL RCRA LISTED WASTES [40 CFR 261.31-33] (Check any that apply)
This section was designed to assist you in determining whether or not your waste is a Federal

Resource Conservation and Recovery Act (RCRA) hazardous waste. Review each step and refer to the attached lists or noted regulations in order to fully determine whether or not the waste or process is located on a list. Check each box that applies to your waste and indicate the Federal EPA Hazardous Waste Code (e.g. F006, U093...) in the space provided. When your waste/process has been matched against each list, a determination has been made, and the appropriate box(es) has been checked, proceed to the next section.

	It is a listed waste from a non-specific (generic) process under the "F" listed waste codes [40 CFR 261.31] WASTE CODE:
	It is a listed waste from a specific process under the "K" listed waste codes [40 CFR 261.32] WASTE CODE:
X	It is not a listed waste under the "F" or "K" listed waste codes.
Di	scarded Commercial Products/Off-spec Products/Container and Spill Residue
	("P" code) WASTE CODE:
	"P" code wastes are considered acutely hazardous wastes (AHW).
	The sole active ingredient is a listed non-process toxic waste per 40 CFR 261.33 ("U" code) WASTE CODE:
	"U" code wastes are used for wastes that are considered toxic, reactive, ignitable, or corrosive.
	It is not a listed waste under the "P" or "U" listed waste codes.
_\ Not	None of the boxes were checked. Thus, the material is not considered a waste. e: if a listed ingredient is not the <i>sole active ingredient</i> , then it is not considered a "U" or waste code.

 $\label{lem:proceed} \begin{tabular}{ll} Proceed to the next Section (Hazardous Waste Physical Characteristics) when complete. \end{tabular}$

HAZARDOUS WASTE PHYSICAL CHARACTERISTICS (Check all that apply)
Below are hazardous waste physical characteristics that may assist you in the process of properly determining whether your waste is hazardous. Reviewing MSDS(s) and other sources of information may be beneficial when completing this section, especially without the use of laboratory analyses. The characteristics of the waste may be obtainable through generator knowledge and/or laboratory analyses. However, it is important to remember that it is the sole responsibility of the generator to properly determine whether the waste is hazardous or not. Be sure you have data to back your determination!

	•
	change
	Compressed gas as defined by 49 Code of Federal Regulations 49 CFR173.300 Material has a pressure > 40 psi @ 70°F or vapor pressure > 40 psi absolute @ 100°F
	Oxidizer as defined by 49 CFR 173.151
-	Releases oxygen when reacting with another chemical
-	Reacts with organic materials (e.g. oils, grease, solvents, paper, cloth, wood, etc.) resulting in fire or generation of heat
	Wastes which may meet this criteria include: solvents, paints, thinners, and adhesives
Th	le waste is corrosive per 40 CFR 261.22 (EPA Hazardous Waste Code: D002)
	Aqueous (liquid) and has a pH < 2 (acid) or > 12.5 (base)
	Solid (non-liquid) when mixed with equal weight of water has a pH < 2 (acid) or > 12.5 (base)
	Dissolves/corrodes steel (SAE 1020) at a rate greater than .25 inch per year
	Wastes which may meet this criteria include: etchants, alkaline degreasers, acids and base
Th	e waste is reactive per 40 CFR 261.23 (EPA Hazardous Waste Code: D003)
	Normally unstable & readily undergoes violent change without detonation
	Reacts violently with water, or forms potentially explosive mixtures with water
	Generates toxic gases, vapors or fumes when mixed with water or air
	Capable of detonation, explosive reaction or explosive decomposition
	Wastes which may meet this criteria include: chromic acids and cyanide compounds

The waste is **toxic** per 40 CFR 261.24 (EPA Hazardous Waste Code: Varies)

Determining whether or not a waste is hazardous due to its toxicity can be a very complicated process. The toxicity characteristic is the most complex characteristic to determine. This characteristic is based on whether or not a waste exceeds concentrations of certain metals and organics based on analytical results from laboratory analyses. The collection and submission of waste samples for each laboratory analysis can become an expensive endeavor. However, it is important to realize that the generator can save a significant amount of money by better understanding the process and the waste generated by the process. Thus, possibly eliminating or reducing the number of samples needed to properly characterize the waste.

Next, are some hazardous waste tables that may be used to assist you in properly characterizing waste streams. In the tables you will find the name of the constituent and the regulatory limit for that constituent and that particular test. During this phase there are

California (Non-RCRA) regulatory limits and Federal (RCRA) regulatory limits. So, be sure to select which test(s) will provide you with the best results to properly classify your waste. The next five tables consist of substances which are known to be hazardous at/above certain regulatory concentrations. The following tables provide you with the constituents and their regulatory limits associated with a specific laboratory analysis. If you are using laboratory analysis results to aid in the determination of your waste, then proceed to check the appropriate box(es) for each constituent that meets and/or exceeds the regulatory limit in the, particular table. If you still have questions regarding toxicity analyses, then proceed to the last page where you can find some additional information regarding toxicity analysis for wastes.

TABLE 1

Threshold Characteristic Leaching Procedure (TCLP) [RCRA] – This analysis helps determine whether a facility's waste is a RCRA hazardous waste and is the least expensive. This analysis should be the first step if you are uncertain what may be in your wastestream or you suspect that your wastestream contains any of the constituents listed below. Compare analytical data to the constituents listed below and determine whether they meet or exceed the regulatory limits in the table. Check the appropriate box(es). If no constituents are identified at or above the listed regulatory limit, proceed to Table 2. Note: The EPA Hazardous Waste Code (in parenthesis) is located next to the regulatory concentration limit for each constituent.

TCLP (mg/l) [40 CFR 261.24(b)(1)]

- ☐ Arsenic > 5.0 mg/l (D004)
- ☐ Barium >100 mg/l (D005)
- ☐ Benzene >0.5 mg/l (D018)
- ☐ Cadmium >1.0 mg/l (D006)
- ☐ Carbon Tetrachloride >0.5 mg/l (D019)
- ☐ Chlordane >0.03 mg/l (D020)
- ☐ Chlorobenzene >100 mg/l (D021)
- ☐ Chloroform >6.0 mg/l (D022)
- ☐ Chromium >5.0 mg/l (D007)
- o-cresol >200.0 mg/l (D023)
- □ m-cresol >200.0 mg/l (D024)
- □ p-cresol >200.0 mg/l (D025)
- ☐ Cresol >200.0 mg/l (D026)
- \square 2,4-D > 10.0 mg/l (D016)
- ☐ 1,4-Dichlorobenzene >7.5 mg/l (D027)
- □ 1,2-Dichloroethane >0.5 mg/l (D028)
- ☐ 1,1-Dichloroethylene >0.7 mg/l (D029)
- □ 2,4-Dinitrotoluene >0.13 mg/l (D030)
- ☐ Endrin >0.02 mg/l (D012)
- ☐ Heptachlor(and epoxide) >.008 mg/l (D031)
- ☐ Hexachlorobenzene >.13 mg/l (D032)
- ☐ Hexachlorobutadiene >0.5 mg/l (D033)
- ☐ Hexachloroethane >3.0 mg/l (D034)
- ☐ Lead > 5.0 mg/l (D008)
- ☐ Lindane >0.4 mg/l (D013)
- ☐ Mercury >0.2 mg/l (D009)
- ☐ Methoxychlor > 10.0 mg/l (D014)
- ☐ Methyl ethyl ketone >200.0 mg/l (D035)
- □ Nitrobenzene >2.0 mg/l (D036)
- ☐ Pentachlorophenol >100.0 mg/l (D037)

□ Pyridine >5.0 mg/l (D038) □ Selenium >1.0 mg/l (D010) □ Silver >5.0 mg/l (D011) □ Tetrachloroethylene >0.7 mg/l (D039) □ Toxaphene >0.5 mg/l (D015) □ Trichloroethylene >0.5 mg/l (D040) □ 2,4,5-Trichlorophenol >400.0 mg/l (D041) □ 2,4,6-Trichlorophenol >2.0 mg/l (D042) □ 2,4,5-TP (Silvex) >1.0 mg/l (D017) □ Vinyl Chloride >0.2 mg/l (D043) □ No testing was conducted.
ADDITIONAL INFORMATION (Check if applies) This waste has been classified using some form of generator knowledge (MSDS, knowledge of similar wastes or process knowledge, etc.). See attached documents which support this determination.
DETERMINATION The material is a hazardous waste. The material is a non-hazardous waste. Other (i.e. universal waste, special waste, etc.). Reasoning: The material is a non-hazardous waste. Other (i.e. universal waste, special waste, etc.). Reasoning: The material is a hazardous waste. Other (i.e. universal waste, special waste, etc.).
Note: attach any and all documentation (i.e. MSDSs, laboratory analyses, generator knowledge, calibration records, etc.) associated with the determination of this waste. This waste may be disposed of at the following facilities:
4/10/2003

Notice of Violation Pursuant to Requirements of the Resource Conservation and Recovery Act (RCRA)

REC'C AUG 28 2006

D: Facility Name:	TIMAX MOLYBDENIIM	RESP
	598 Highway 61	.1201
EPA ID Number:	ort Madison, IA 52627	
EFA ID Number:	AD000222033	Date: 8-22-04
is notice is provided to	call your attention to the following	g areas of noncompliance with state and federal regulations.
		trative Civil Complaint) pursuant to Section 3008 of RCRA
d may not be a complete	te listing of all violations resulting	from the the inspection.
Citation		Description of Violation
40 CFR 279.12	(c) 1650.	DIL CONTAINERS DOT LABELE
The plant of the party		012."
40 CFR 262.11	<u> </u>	TO MAKE NAZARDOMS
	WASTE	DETERMINATIONS ON:
	1) 3.	AT HOUSE DUST
		FUT PARTS WASHED SHOVENT
	2152	FINI TAKIS WIASHAR SELVENT
	The state of the s	
	The state of the s	
ou are requested to sub	omit a written response within 14 c	alendar days of receipt of this notice. Your response should
		schedule for completing the necessary corrective actions.
he response should be s		sometime for completing the necessary corrective actions.
no response snould be s	domittod to.	
	II S Environmental Prof	tection Agency, Region VII
	Federal Building 210 Walnut Stree	
	Des Moines, IA 5	10309-2109
	ATTN. GARY R. WIT	KOVSKI
f you have any question	s about this Notice or wish to discu	ss your response, you may call me at
(515) 284-	4029 , or JAMES AYCOCK	(Compliance Officer) a
(913) 551-	7887	
his Notice prepared by	GARY R. WITKOVSKI	Date: 8-22-01
ms rectice propared by	GOVI V. MITVOADVI	Date. 227 02
Manual		and a conversable Newscard by
ne undersigned person	acknowledges that he/she has received	ved a copy of this Notice and has read same.
		I the lakes along
	Printed Name:)cott 1ckes, Date: 8/22/06
	Signature:	*oll she
	Title: Mar	of DA and Environmental Affairs